



**JT8D LIFE LIMITED PARTS STATUS**

**ENGINE MODEL: JT8D-15**

**ENGINE SERIAL NUMBER: 685538**

**CUSTOMER: GLOBAL**

**ENGINE TOTAL TIME: 70,510:45**

**ENGINE TOTAL CYCLES: 49,732**

**WORK ORDER: 06106**

| DISC STAGE        | PART NUMBER       | SERIAL NUMBER     | HOUR LIMIT   | CYCLE LIMIT  | HOURS USED      | CYCLES USED | HOURS REMAIN    | CYCLES REMAIN |
|-------------------|-------------------|-------------------|--------------|--------------|-----------------|-------------|-----------------|---------------|
| <b>LPC MODULE</b> |                   |                   |              |              |                 |             |                 |               |
| <b>C-1</b>        | <b>817401</b>     | <b>T78662</b>     | <b>UNL</b>   | <b>20000</b> | <b>9601</b>     | <b>6837</b> | <b>N/A</b>      | <b>13163</b>  |
| <b>C-2</b>        | <b>790832</b>     | <b>BBDUAX4482</b> | <b>30000</b> | <b>20000</b> | <b>14504.18</b> | <b>8918</b> | <b>15495.82</b> | <b>11082</b>  |
| <b>C-3</b>        | <b>799773</b>     | <b>BBDUAX3663</b> | <b>30000</b> | <b>20000</b> | <b>14504.18</b> | <b>8918</b> | <b>15495.82</b> | <b>11082</b>  |
| <b>C-4</b>        | <b>799504</b>     | <b>BBDUAO0062</b> | <b>30000</b> | <b>20000</b> | <b>14504.18</b> | <b>8918</b> | <b>15495.82</b> | <b>11082</b>  |
| <b>C-5</b>        | <b>745705</b>     | <b>BBDUAO1666</b> | <b>30000</b> | <b>20000</b> | <b>14504.18</b> | <b>8918</b> | <b>15495.82</b> | <b>11082</b>  |
| <b>C-6</b>        | <b>745706</b>     | <b>BBDUAX3269</b> | <b>30000</b> | <b>20000</b> | <b>14504.18</b> | <b>8918</b> | <b>15495.82</b> | <b>11082</b>  |
| <b>HPC MODULE</b> |                   |                   |              |              |                 |             |                 |               |
| <b>C-7</b>        | <b>815607-002</b> | <b>BENCAP2637</b> | <b>30000</b> | <b>20000</b> | <b>14504.18</b> | <b>8918</b> | <b>15495.82</b> | <b>11082</b>  |
| <b>C-8</b>        | <b>815708-002</b> | <b>BENCAS4694</b> | <b>30000</b> | <b>20000</b> | <b>14504.18</b> | <b>8918</b> | <b>15495.82</b> | <b>11082</b>  |
| <b>C-9</b>        | <b>822109</b>     | <b>BENCAY5644</b> | <b>30000</b> | <b>20000</b> | <b>0</b>        | <b>0</b>    | <b>30000</b>    | <b>20000</b>  |
| <b>C-10</b>       | <b>815610-002</b> | <b>BENCAS4584</b> | <b>30000</b> | <b>20000</b> | <b>14504.18</b> | <b>8918</b> | <b>15495.82</b> | <b>11082</b>  |
| <b>C-11</b>       | <b>815611-001</b> | <b>BENCAT1237</b> | <b>30000</b> | <b>20000</b> | <b>4535.5</b>   | <b>3146</b> | <b>25464.5</b>  | <b>16854</b>  |
| <b>C-12</b>       | <b>798512-001</b> | <b>BENCAN2913</b> | <b>30000</b> | <b>20000</b> | <b>7251.6</b>   | <b>3980</b> | <b>22748.4</b>  | <b>16020</b>  |
| <b>C-13</b>       | <b>5003613-01</b> | <b>S62103</b>     | <b>30000</b> | <b>20000</b> | <b>4715.2</b>   | <b>3453</b> | <b>25284.8</b>  | <b>16547</b>  |
| <b>HPT MODULE</b> |                   |                   |              |              |                 |             |                 |               |
| <b>T-1</b>        | <b>856501</b>     | <b>BKLBC72936</b> | <b>30000</b> | <b>20000</b> | <b>14504.18</b> | <b>8918</b> | <b>15495.82</b> | <b>11082</b>  |
| <b>LPT MODULE</b> |                   |                   |              |              |                 |             |                 |               |
| <b>T-2</b>        | <b>803122*</b>    | <b>BLDLC28761</b> | <b>30000</b> | <b>20000</b> | <b>38251.21</b> | <b>3055</b> | <b>-8251.21</b> | <b>16945</b>  |
| <b>T-3</b>        | <b>795603</b>     | <b>T72090</b>     | <b>30000</b> | <b>20000</b> | <b>11661.57</b> | <b>7529</b> | <b>18338.43</b> | <b>12471</b>  |
| <b>T-4</b>        | <b>769104</b>     | <b>BLDLCN7724</b> | <b>30000</b> | <b>20000</b> | <b>14504.18</b> | <b>8918</b> | <b>15495.82</b> | <b>11082</b>  |

CW AD 86-09-02 install Cat 2A Chambers

CW AD 2003-12-07 ASB 6431 8 year re-inspection interval

CW AD 2005-25-05 and 2010-21-17 Overhauled C1 Disk & Blades

**TMC Engine Center, Inc.**

FAA repair Station No. Z5LR447Y

7905 NW 77th Ave. Medley, FL 33166 Phone: 786-337-6650 Fax: 786-337-6610